

AD-A106 047


ARMY ENGINEER DISTRICT MEMPHIS TN
NATIONAL DAM SAFETY PROGRAM. TEMPLES LAKE DAM (MO 40065), LOWER-ETC(U)
MAR 80 J L ANDERSON, W J SELVO, R M DAVIS

F/G 13/13

UNCLASSIFIED

NL

1 of 1
40 A
0604*



AD A106047

SECRET

SECRET

This document contains neither
recommendations nor conclusions of
the FBI. It is the property of the
FBI and is loaned to your agency;
it and its contents are not to be
distributed outside your agency.

DISTRIBUTION STATEMENT A
Approved for public release;
Distribution Unlimited

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. AD-A106 047	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Temples Lake Dam (MO 40065) Stoddard County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report
7. AUTHOR(s) Corps of Engineers, Memphis District		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		8. CONTRACT OR GRANT NUMBER(s) N/A
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING National Dam Safety Program. Temples Lake Dam (MO 40065). Lower Mississippi St. Francis Basin, Stoddard County, Missouri. Phase I Inspection Report.		12. REPORT DATE March 1980
16. DISTRIBUTION Approved for release; distribution unlimited.		13. NUMBER OF PAGES Approximately 35
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
18. SUPPLEMENTARY NOTES		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		


DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

TEMPLES LAKE DAM
STODDARD COUNTY, MISSOURI

MISSOURI INVENTORY NO. 40065

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

DTIC
ELECTE
OCT 21 1981
D

PREPARED BY: ST. LOUIS DISTRICT CORPS OF ENGINEERS
FOR: GOVERNOR OF MISSOURI

MARCH 1980

DISTRIBUTION STATEMENT A
Approved for public release;
Distribution Unlimited

PHASE I REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam	Temples Lake Dam
State Located	Missouri
County Located	Stoddard County
Stream	St. Francis River
Date of Inspection	21 May 1979

The Temples Lake Dam was inspected by an interdisciplinary team of engineers from the Memphis District, U. S. Army Corps of Engineers. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

The guidelines used in the assessment were furnished by the Department of the Army, Office of the Chief of Engineers and developed with the help of several Federal and state agencies, professional engineering organizations, and private engineers. Based on these guidelines, this dam is classified as a small size dam with a high downstream hazard potential. Failure would threaten the life and property of two families downstream of the dam.

The inspection and evaluation indicate that the spillway is adequate and does meet the criteria set forth in the guidelines for a dam having the above mentioned size classification and hazard potential. For its size and hazard category, this dam is required by the guidelines to pass from one-half PMF to PMF. However, several considerations were given to selecting the appropriate spillway design flood. There were only two family dwellings downstream of the dam and one dwelling was uninhabited at the time of the inspection. Also, the owner has breached the guide levee (which increases the outflow quantity considerably) during times of high reservoir levels in the past and it is his intention to do so again if the need ever arises. Hence, considering the small number of dwellings and property downstream of the dam and the past operational procedures of the owner, the one-half PMF is considered the appropriate spillway design flood. The spillway (with the guide levees in place) will pass both the 100-year flood and one-half PMF without the dam overtopping. The 100-year flood is a flood which has a 1 percent chance of being exceeded in any given year. There are no other hydrologic or hydraulic deficiencies.

Deficiencies visually observed by the inspection team were minor erosion gullies on the downstream embankment slope and minor wavewash on the upstream embankment slope. Another deficiency found was the lack of seepage and stability analysis records.

Accession For	NTIS <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
DTIC TAB	
Unannounced	
Justification	
By	
Distribution/	
Availability Codes	
Avail and/or	
Rest Special	

It is recommended that the owner take action to correct or control the deficiencies described. Corrective works should be in accordance with analyses and design performed by an engineer experienced in the design and construction of dams.

Jerry L. Anderson
JERRY L. ANDERSON
Hydraulic Engineer
Memphis District
Corps of Engineers

Robert M. Davis
ROBERT M. DAVIS
Geologist
Memphis District
Corp of Engineers

William J. Selvo
WILLIAM J. SELVO
Soils Engineer
Memphis District
Corps of Engineers

SIGNED

SUBMITTED BY: _____
Chief, Engineering Division

14 APR 1980

Date

APPROVED BY: _____
Colonel, CE, District Engineer

SIGNED

14 APR 1980

Date



Overview of Lake

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
TEMPLES LAKE DAM - ID NO. 40065

TABLE OF CONTENTS

<u>Paragraph No.</u>	<u>Title</u>	<u>Page No.</u>
1.1	General	1
1.2	Description of Project	1
1.3	Pertinent Data	2
SECTION 2 - ENGINEERING DATA		
2.1	Design	5
2.2	Construction	5
2.3	Operation	5
2.4	Evaluation	5
SECTION 3 - VISUAL INSPECTION		
3.1	Findings	6
3.2	Evaluation	7
SECTION 4 - OPERATIONAL PROCEDURES		
4.1	Procedures	8
4.2	Maintenance of Dam	8
4.3	Maintenance of Operating Facilities	8
4.4	Description of Any Warning System in Effect	8
4.5	Evaluation	8
SECTION 5 - HYDRAULIC/HYDROLOGIC		
5.1	Evaluation of Features	9
SECTION 6 - STRUCTURAL STABILITY		
6.1	Evaluation of Structural Stability	10
SECTION 7 - ASSESSMENT/REMEDIAL MEASURES		
7.1	Dam Assessment	11
7.2	Remedial Measures	11

TABLE OF CONTENTS (Cont'd)

LIST OF PLATES

<u>Plate No.</u>	<u>Title</u>
1	Location Map
2	Vicinity Topography
3	Dam Plan View - NTS
4	Centerline Profile
5	Dam Cross-Section
6	Guide Levee profiles
7	Guide Levee Sections D and E
8	Guide Levee Section F

APPENDIX

A	Hydrology and Hydraulics
---	--------------------------

LIST OF PHOTOGRAPHS

<u>Photo No.</u>	<u>Title</u>
1	Centerline of Dam from the Left Abutment
2	Downstream Slope from Right Abutment
3	Upstream Slope from Left Abutment
4	Wavewash on Upstream Slope
5	Erosion Area
6	Marshy Area near Downstream Toe and Emergency Spillway

TABLE OF CONTENTS (Cont'd)

<u>Photo No.</u>	<u>Title</u>
7	Inlet Pipe
8	Outlet Pipe
9	Emergency Spillway
10	Guide Levee between Farm Pond and Lagoon
11	Farm Pond
12	Lagoon
13	Floodplain Downstream of Dam
14	Dwelling Downstream of Dam
15	Uninhabited Dwelling Downstream of Dam

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the District Engineer for the St. Louis District, Corps of Engineers, directed that a safety inspection of Temples Lake Dam be made.

b. Purpose of Inspection. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

c. Evaluation Criteria. Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams." These guidelines were developed with the help of several Federal agencies and many state agencies, professional engineering organizations, and private engineers.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances.

(1) The dam is an earthen structure built on a plateau in the uplands which border the Mississippi Embayment. Topography adjacent to the valley is gently rolling. Soils in the area are formed of silty clays. Topography in the vicinity of the dam is shown on Plate 2.

(2) A 8-inch diameter smooth iron pipe with a canopy inlet and trash rack sloping through the embankment for a horizontal distance of 98 feet on a slope of approximately 1V on 9.25H is the primary means of discharge. An earthen emergency spillway is cut in the right abutment. The emergency spillway is a triangular section with a left side slope of 1V on 6.25H and right side slope of 1V on 8.2H. The average depth is 5 feet. The discharge of the emergency spillway empties into a side channel that extends for a distance of approximately 700 feet where it connects to a farm pond. (See Plate 3).

(3) Pertinent physical data are given in paragraph 1.3 below.

b. Location. The dam is located in the south central portion of Stoddard County, Missouri, as shown on Plate 1. The lake formed by the dam as shown on Plate 2 is located on the Valley Ridge, Missouri Quadrangle sheet in Section 25; Township 24 North; Range 9 East.

c. Size Classification. Criteria for determining the size classification of dams and impoundments are presented in the guidelines referenced in paragraph 1.1c above. Based on these criteria, this dam and impoundment is in the small size category.

d. Hazard Classification. Guidelines for determining hazard classification are presented in the same guidelines as referenced in paragraph c above. Based on referenced guidelines, this dam is in the High Hazard Classification.

e. Ownership. The dam is owned by Mr. Kenneth Temples, Route 3, Dexter, Missouri 63841.

f. Purpose of Dam. The dam forms a 9-acre farm pond.

g. Design and Construction History. The dam was constructed in 1974 by the present owner, Mr. Kenneth Temples. There were no design plans. Borrow material for the construction of the dam consisted of the native clay which was taken from the lake area and from the surrounding hills. The effort utilized in compacting the embankment is unknown. The dam reportedly has a core trench, however, the dimensions of the trench are not known. A guide levee on the downstream side of the emergency spillway channel connects to a farm pond about 700 feet from the centerline of the main dam (See Plate 3). The owner reported that on some occasions he has breached the guide levee that forms the side channel to relieve the dam of rising water levels.

h. Normal Operating Procedure. Normal rainfall, runoff, transpiration, and evaporation all combine to maintain a relatively stable water surface elevation. However, at the time of the inspection, the owner was draining the lake with a PVC siphon pipe inserted within the primary discharge pipe.

1.3 PERTINENT DATA

a. Drainage Area - 185 acres (Topographic Quadrangle)

b. Discharge at Damsite.

(1) Discharge can take place through a canopy pipe inlet and an emergency spillway. The flow is contained within a guide levee until elevation 347.6 N.G.V.D. Then flow will overtop portions of the guide levee.

(2) Estimated experienced maximum flood at damsite - unknown.

c. Elevation (Feet above N.G.V.D.)

- (1) Observed Pool - 344.0
- (2) Normal Pool - 343.9
- (3) Spillway Crest
 - (i) Main Spillway - 344.0
 - (ii) Guide levee - 347.6

- (4) Maximum Experienced Pool - Unknown
- (5) Top of Dam - 350.7
- (6) Maximum Pool
 - (i) PMF - 351.2
 - (ii) $\frac{1}{2}$ PMF - 350.2
- (7) Invert of Discharge Pipe at Stilling Basin - 330.3
- (8) Streambed at centerline of dam - 324.5
- (9) Maximum Tailwater - Unknown

d. Reservoir. Length of maximum pool - 1400+ feet.

e. Storage. (Acre - feet)

- (1) Observed Pool - 41
- (2) Normal Pool - 40
- (3) Spillway Crest
 - (i) Main spillway - 41
 - (ii) Guide levee - 74
- (4) Maximum Experienced Pool - Unknown
- (5) Top of Dam - 108
- (6) Maximum Pool
 - (i) PMF - 113
 - (ii) $\frac{1}{2}$ PMF - 102

f. Reservoir Surface Area (Acres)

- (1) Observed Pool - 8.63
- (2) Normal Pool - 8.57
- (3) Spillway Crest
 - (i) Main spillway - 8.63
 - (ii) Guide levee - 10.85
- (4) Maximum Experienced Pool - Unknown
- (5) Top of Dam - 12.76
- (6) Maximum Pool
 - (i) PMF - 13.07
 - (ii) $\frac{1}{2}$ PMF - 12.46

g. Dam.

- (1) Type - earth embankment
- (2) Length - 370+ feet
- (3) Height - 26.2 feet Maximum
- (4) Top Width - 13+ feet
- (5) Side Slopes
 - (a) Downstream - 1V on 3.12H
 - (b) Upstream - 1V on 3.54H

- (6) Impervious core - Reported by owner - no verification.
- (7) Cutoff - Unknown
- (8) Grout curtain - Unknown

h. Diversion and Regulating Tunnel. None.

i. Primary Discharge System.

(1) Type - An uncontrolled 8-inch diameter smooth iron pipe with a canopy inlet and trash rack sloping through the embankment on slope of 1V on 9.25H. (See paragraph 1.2a).

- (2) Horizontal length of 8-inch diameter pipe - 98 feet
- (3) Invert elevation of inlet - 343.9 N.G.V.D.
- (4) Invert elevation of outlet - 330.3 N.G.V.D.

j. Emergency Spillway.

- (1) Type - Uncontrolled earthen triangular section.
- (2) Width of weir - N/A
- (3) Average depth - 5 feet
- (4) Length of discharge channel - approximately 700 feet.
- (5) Side Slopes
 - (i) Left - IV on 6.25H
 - (ii) Right - IV on 8.2H
- (6) Crest Elevation
 - (i) Main Spillway - 344.0 N.G.V.D.
 - (ii) Guide levee - 347.6 N.G.V.D

k. Regulating Outlet. None.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

No design data exists.

2.2 CONSTRUCTION

The dam was constructed in 1974 by the present owner, Mr. Kenneth Temples. Borrow material for the construction of the dam consisted of the native clay which was taken from the lake area and from the surrounding hills. The effort utilized in compacting the embankment is unknown. The dam reportedly has a core trench, however, the dimensions of the trench are not known.

2.3 OPERATION

The primary means of discharge is the 8-inch smooth iron pipe. Emergency discharge can take place through the emergency spillway located in the right abutment. Both structures are uncontrolled and normal rainfall, runoff, and evaporation coupled with the uncontrolled discharges combine to maintain a rather stable water surface. Discharges from the lake flow along the spillway channel and for elevations less than 347.6 N.G.V.D. will flow into another farm pond. For elevation greater than 347.6 N.G.V.D. flow will pass over the guide levee into the floodplain below dam.

2.4 EVALUATION

a. Availability. The only engineering data readily available are the personal recollections of the present and previous owners.

b. Adequacy. The field and visual inspections presented herein are considered adequate to support the conclusions of this report. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.

c. Validity. Not applicable.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General. Visual inspection of Temples Lake Dam was performed on 21 May 1979. Personnel making the inspection were employees of the Memphis District, Corps of Engineers, and included a geologist, hydraulic engineer, and soils engineer. Specific observations are discussed below.

b. Project Geology. The dam is located on the Monadnockic Remnant of the Pleistocene Uplands of the Mississippi River Embayment. In the local area, this section is called Crowleys Ridge. Crowleys Ridge is the remnant of the Pleistocene which formerly covered the Mississippi Embayment area prior to its dissection by the Mississippi-Ohio River complex. Geological sections indicate that Crowleys Ridge consists of a loess mantle covering the Pleistocene which is underlain by the Wilcox Group of the Lower Eocene. The loess consists of predominantly silt sized particles while the Pleistocene is a coarse sand at the top, grading to a gravel on top of the Tertiary. In this area, the Wilcox Group is the Ackerman formation which is the light gray to brown silty non-marine clay. The dam is located in a Seismic Zone 3.

c. Dam. Based on the cross-section presented on Plate 5, the dam has an average upstream embankment slope of 1V on 3.54H and an average downstream slope of 1V on 3.12H. The crown width of the dam is 13 feet. The visual inspection indicates no evidence of any undue settlement, cracking or sliding of the dam. No animal burrows were observed in the dam. The crest and slopes are very well grassed and maintained. (See Photos 1, 2, and 3).

The upstream embankment has no erosion protection and some minor wavewash has occurred intermittently along the upstream face (See Photo 4). Minor erosion appears on the downstream face of dam; however, this appears to have been caused by the use of this portion of the dam by cattle. (See Photo 5). Also a marshy area was observed on the downstream toe of the embankment near the emergency spillway (See Photo 6). No evidence of piping material or seepage flow was observed. The area appeared to be a low marshy area.

d. Appurtenant Structures. An 8-inch diameter smooth iron pipe with a canopy inlet and trash rack is the primary means of discharge. At the time of the inspection the trash rack had been removed. The lake was also being drained by a siphon constructed of PVC pipe inserted within the main discharge pipe. (See Photo 7). Minor seepage flow with a reddish iron oxide tint was observed in the area of the outlet. No piping of dam material was observed. Willow trees and cattails grew abundantly in the area. (See Photo 8). An earthen V-shaped emergency spillway was cut in the right abutment. The discharge of the emergency spillway empties into a side channel that extends for a distance of approximately 700 feet. The channel then connects to a small farm pond. The emergency spillway and side channel are very well maintained. (See Photos 9 and 10). Plate 6 shows the centerline profile of the top of the guide levee and the centerline of the bottom of the emergency spillway channel from the main dam to the farm pond.

Plates 7 and 8 show cross-section along the emergency spillway channel as depicted on Plate 3. Photos 11 and 12 show the farm pond and lagoon respectively.

e. Reservoir Area. No wavewash, excessive erosion, or slides were observed along the shoreline of the reservoir.

f. Downstream Channel. The downstream channel is overgrown with trees and brush. However, the flood plain immediately downstream is pastureland. (See Photo 13).

3.2 EVALUATION

None of the conditions observed are significant enough to indicate a need for immediate remedial action. However, the minor wavewash and minor erosion gullies on the downstream embankment slope of the dam should be corrected or controlled.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

The primary discharge system and emergency spillway are uncontrolled; therefore, no regulating procedure exists for these structures. The pool is controlled by rainfall, runoff, evaporation, and capacity of the uncontrolled discharge system. Discharges from the lake flow along the spillway channel and for elevation less than 347.6 N.G.V.D. flow will pass over the guide levee into the floodplain below the dam.

4.2 MAINTENANCE OF DAM

In the past, the guide levee has been breached by the owner during times of high water level in the reservoir to enhance the discharge potential of the main spillway exit section. The dam and discharge structures are all very well maintained.

4.3 MAINTENANCE OF OPERATING FACILITIES

No operating facilities exist at this dam.

4.4 DESCRIPTION OF ANY WARNING SYSTEM

The inspection team is not aware of any existing warning system for this dam.

4.5 EVALUATION

The maintenance of the dam is adequate.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

a. Design Data. There was no hydraulic nor hydrologic design data to evaluate.

b. Experience Data. The drainage area was developed using USGS Valley Ridge, Missouri Quadrangle. The spillway and dam layout are made from surveys conducted by the inspecting team.

c. Visual Observation.

(1) The primary means of discharge is through an 8-inch diameter smooth iron pipe as discussed in para 1.3i.

(2) The emergency discharge is through a triangular shape ditch as discussed in para 1.3j.

(3) Both discharge structures are very well maintained.

(4) The emergency spillway channel is connected to a farm pond approximately 700 ft. downstream from the centerline of the dam. On occasion, the flow from the emergency spillway could act as a source of water for the downstream pond (See Plate 3 and Photos 9, 10, 11, and 12).

d. Overtopping Potential. The spillway will safely pass one-half of the Probable Maximum Flood (PMF) at a discharge of 860 cfs without overtopping. The Probable Maximum Flood is defined as the flood discharge that may be discharged from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. The 100-year frequency flood will not overtop the embankment. For its size and hazard category, this dam is required by the guidelines to pass from one-half PMF to PMF. However, several considerations were given to selecting the appropriate spillway design flood. There were only two family dwellings downstream of the dam and one dwelling was uninhabited at the time of the inspection. Also, in the past, the owner has breached the guide levee during times of high reservoir levels to increase the flows through the principal emergency spillway section. Hence considering the small number of dwellings and property downstream of the dam and the past maintenance procedures of the owner, the one-half PMF is considered the appropriate spillway design. The data utilized in the preparation of the estimates was various Federal reports, data from field inspection and survey, and output from COE program HEC-1, Dam Safety Version. More specific details will be found in Appendix A.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observation. Visual observations of the dam and appurtenant structures are discussed and evaluated in SECTIONS 3 and 5.

b. Design and Construction Data. The design and construction data were limited to that information discussed in SECTION 2.

c. Operation Records. There have been no known operations which have affected the structural stability of the dam.

d. Post Construction Changes. No post construction changes exist which will affect the structural stability of the dam.

e. Seismic Stability. This dam is located in Seismic Zone 3. Since this dam is located in Seismic Zone 3, it is possible that an earthquake could occur of sufficient intensity to cause severe damage or failure of the dam.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Safety. Several items were noted during the visual inspection which should be corrected or controlled. The marshy area on the downstream toe near the emergency spillway area, the seepage observed at the outlet, the minor wave wash on the upstream slope, and the small erosion gullies are the items of concern. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record. One-half of the probable Maximum Flood (the spillway design flood) will not overtop the dam.

b. Adequacy of Information. Due to the lack of engineering design and construction data, the conclusions in this report were based on performance history and external visual conditions. The inspection team considers that these data are sufficient to support the conclusions herein.

c. Urgency. The remedial measures recommended in paragraph 7.2 should be accomplished in the near future. The stability and seepage analyses should be given priority by the owner and accomplished without delay in order to determine if corrective measures are necessary.

d. Necessity for Phase II. Based on the results of the Phase I inspection, no Phase II inspection is recommended.

e. Seismic Stability. This dam is located in Seismic Zone 3. Since this dam is located in Seismic Zone 3, it is possible that an earthquake could occur of sufficient intensity to cause severe damage or failure of the dam.

7.2 REMEDIAL MEASURES


a. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available which is considered a deficiency. These seepage and stability analyses should be performed for the appropriate loading conditions (including earthquake loads) and made a matter of record.


b. O & M Maintenance and Procedures. The following O & M maintenance and procedures are recommended:

(1) The minor wave wash of the upstream embankment slope and the minor erosion gullion on the downstream embankment slope should be corrected or controlled.


(2) Periodic inspection of dam to ascertain if any additional seepage problems occur or the ones noted begin to pipe dam material.


(3) A detailed inspection of the dam should be made at least every 5 years by an engineer experienced in design and construction of dams.






TEMPLES LAKE
VICINITY TOPOGRAPHY
PLATE 2






TEMPLES LAKE
CENTERLINE PROFILE
PLATE 4

TEMPLES LAKE
DAM CROSS-SECTION
PLATE 5





TEMPLES LAKE
GUIDE LEVEE PROFILE
PLATE 6

TEMPLES LAKE
GUIDE LEVEE SECTIONS D&E
PLATE 7

120 80 40 0 40 80

355

FL. N.G.V.D.

345

335

Section D


355

FL. N.G.V.D.


345

335

Section E



TEMPLES LAKE
GUIDE LEVEE SECTION F
PLATE 8



APPENDIX A

Hydrology and Hydraulic

1. Narrative. The methods and sources of data were primarily those suggested by the Hydraulics Branch, St. Louis District, Corps of Engineers. Specific references and methods will be discussed below. A field inspection survey was made to determine the outlet structures and the topographic characteristics of the dam. HEC-1, Dam Safety Version was used in conjunction with appropriate input parameters to compute inflow hydrographs, determine storage, and route through the structure.

a. Rainfall. The PMF was developed using Hydrometeorological Report No. 33. The "Hop Brook" reduction factor was not used to adjust the rainfall for this study. The distribution of rainfall was developed using the criteria as described by EM 1110-2-1411 (Standard Project Storm).

PMF Rainfall	27.1 inches
PMF Percentages	6 hr - 102
	12 hr - 120
	24 hr - 130
	48 hr - 140

b. Unit Hydrograph Coefficients. The unit hydrograph for the drainage basin was developed using the Snyder Method as outlined in HEC-1, Dam Safety Version. Two methods of determining time of concentration were used, namely the Snyder's method and Kirpich method for comparative purposes.

The variables used for the appropriate method are listed below.

Snyder's: $t_p = C_t (L L_{ca})^{0.3}$; L and L_{ca} in miles

$L = 5830 \text{ feet} = 1.10 \text{ miles}$

$L_{ca} = 2710 \text{ feet} = 0.51 \text{ miles}$

Stream Slope = 59 ft/mi. = .0112 ft/ft

$C_t = .72$

$t_p = .61 \text{ hr}$

$t_c = .71 \text{ hr}$

Kirpich: $t_c = .00013$

$$\left(\frac{L, \text{ ft}}{\sqrt{\text{Slope, ft/ft}}} \right)^{.77}$$

$t_c = .58 \text{ hr}$

Where

L = length of the main stream channel from the outlet to the divide.

L_{ca} = length along the main channel to a point opposite the watershed centroid.

C_t = coefficient used in Snyder's method.

t_p = time to peak (hr)

t_c = time of concentration (hr)

Consequently, since the time of concentrations agreed so closely, a value for t_p was chosen to be .61 hr or 36.6 minutes which necessitated developing a 10-minute unit hydrograph and applying a 48 hr rainfall to develop the inflow hydrographs.

The general soils map of Stoddard County indicates that Temples Lake Dam lies in an area where the soil is of the Loring-Memphis Association which is a well to moderately well drained medium textured soil on the sloping uplands of Crowley's Ridge. This places the area in a Soil Group C/B. The primary soil cover consists of woods and pasture in a fair hydrologic condition which gives a value of CN of 80 for antecedent moisture condition III. Consequently a value of $C_p = .65$ was chosen as the runoff parameter to be used in Snyder's method.

Listed below are the remaining parameters necessary to develop the unit hydrograph of 10-minute duration.

$$C_p = .649$$

$$\text{Drainage Area} = .289 \text{ sq. mi.}$$

The unit hydrograph ordinates are found in the computer printout.

c. Loss Rates. A loss rate of .5 in. initially and .05 in./hr. was chosen based upon engineering experience.

d. Base Flow and Antecedent Flood Conditions. A base flow of 1 cfs was selected and the routing was started at elevation 347.6 N.G.V.D. in the emergency spillway which corresponds to the low point on the top of the guide levee.

e. Hydrograph Routing. HEC-1, Dam Safety Version uses the single routing step of the "Modified Puls" method. Routing through the emergency spillway and over the embankment was accomplished using the non-level dam top option of the HEC-1, Dam Safety Version (See Plate 3) coupled with critical energy consideration of the flow. The routing through the canopy inlet structure was obtained considering pipe full conditions with the following assumptions:

Primary Discharge Structure

D = 8 inch smooth iron pipe

L = 98 feet

n = .016

head losses:

$$h_{\text{ent}} = \frac{V^2}{2g}$$

$$h_{\text{exit}} = \frac{V^2}{2g}$$

h_f = friction loss (Manning's Equation)

$$Q = .3248 A_g \sqrt{2g} H^{1/2}$$

The invert elevation from which to calculate H, height of head, is 330.7 N.G.V.D. The flow was calculated by hand as input into computer program on Y4 and Y5 cards for elevation and discharge, respectively.

f. Storage. The storage was calculated with the HEC-1, Dam Safety Version with input consisting of elevations and respective surface area which were determined using the USGS Valley Ridge, MO Quadrangle.

 FLOOD HYDROGRAPH PACKAGE (HCC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 10 JAN 80

NON-FEDERAL DAM INSPECTION									
DAM #40065									
TEMPLE'S DAM									
	0	10	20	30	40	50	60	70	80
1	300	0	10	20	30	40	50	60	70
2	5	9	1	.25	.3	.35	.4	.5	1.
3	1	.15	.2	.25	.3	.35	.4	.5	1.
4	1	.1	.2	.25	.3	.35	.4	.5	1.
5	1	.1	.2	.25	.3	.35	.4	.5	1.
6	1	.1	.2	.25	.3	.35	.4	.5	1.
7	1	.1	.2	.25	.3	.35	.4	.5	1.
8	1	.1	.2	.25	.3	.35	.4	.5	1.
9	1	.1	.2	.25	.3	.35	.4	.5	1.
10	1	.1	.2	.25	.3	.35	.4	.5	1.
11	1	.1	.2	.25	.3	.35	.4	.5	1.
12	1	.1	.2	.25	.3	.35	.4	.5	1.
13	1	.1	.2	.25	.3	.35	.4	.5	1.
14	1	.1	.2	.25	.3	.35	.4	.5	1.
15	1	.1	.2	.25	.3	.35	.4	.5	1.
16	1	.1	.2	.25	.3	.35	.4	.5	1.
17	1	.1	.2	.25	.3	.35	.4	.5	1.
18	1	.1	.2	.25	.3	.35	.4	.5	1.
19	1	.1	.2	.25	.3	.35	.4	.5	1.
20	1	.1	.2	.25	.3	.35	.4	.5	1.
21	1	.1	.2	.25	.3	.35	.4	.5	1.
22	1	.1	.2	.25	.3	.35	.4	.5	1.
23	1	.1	.2	.25	.3	.35	.4	.5	1.
24	1	.1	.2	.25	.3	.35	.4	.5	1.
25	1	.1	.2	.25	.3	.35	.4	.5	1.
26	1	.1	.2	.25	.3	.35	.4	.5	1.
27	1	.1	.2	.25	.3	.35	.4	.5	1.

PROBABLE MAXIMUM PRECIPITATION=48 HR DURATION
 .2891 1.
 130 140 .5 .05

ROUTED FLOWS THROUGH TEMPLE'S DAM									
	0	10	20	30	40	50	60	70	80
1	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
2	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
3	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
4	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
5	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
6	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
7	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
8	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
9	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
10	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
11	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
12	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
13	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
14	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
15	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
16	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
17	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
18	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
19	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
20	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
21	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
22	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
23	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
24	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
25	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
26	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5
27	347.6	348.9	349.2	350.5	350.7	350.7	350.7	351.0	351.5

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 10 JAN 80

RUN DATE: 11 JAN 80
 TIME: 11.25.24

NON-FEDERAL DAM INSPECTION
 DAM #40065
 TEMPLE'S DAM

JOB SPECIFICATION
 NQ NHR NMIN IDAY IMR IMIN METRC IPLT IPRT NSTAN
 300 0 10 -0 -0 -0 -0 -0
 JOPER NWT LROPT TRACE
 5 -0 -0 -0

MULTI-PLAN ANALYSES TO BE PERFORMED
 NPLAN= 1 NRTIO= 9 LMTIO= 1

WTIOS= .10 .15 .20 .25 .30 .35 .40 .50 1.00

SUB-AREA RUNOFF COMPUTATION

PROBABLE MAXIMUM PRECIPITATION=48 HR DURATION

ISTAD ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUIO
 1 0 -0 -0 -0 -0 1 -0 -0

HYDROGRAPH DATA

IMYDG IUNG TAREA SNAP TRSDA TRSPC RATIO ISNOW ISAME LOCAL
 1 1 .29 -0. .29 1.00 -0. -0 -0 -0

PRECIP DATA

SPE PM9 R6 R12 R24 R48 R72 R96
 -0. 27.10 102.00 120.00 130.00 140.00 -0. -0.

LOSS DATA

LROPT STRKR DLTKH RTIOL ERAIN STRKS RTIOK STRTL CNSTL ALSHX RTIMP
 -0 -0. -0. 1.00 -0. -0. 1.00 .50 .05 -0. -0.

UNIT HYDROGRAPH DATA
 TP= .61 CPS .65 NTA= -0

RECESSION DATA

STRIO= 1.00 UNCSN= 1.00 RTIOR= 2.00
 APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC= 4.25 AND H= 3.14 INTERVALS

UNIT HYDROGRAPH 19 END-OF-PERIOD ORIGINATES, LAG= .61 HOURS, CP= .65 VOL= 1.00
 25. 66. 158. 195. 176. 131. 95. 69. 50. 36.
 26. 19. 14. 10. 7. 5. 4. 3. 2.

0 MO.DA HR,MN PERIOD MAIN EXCS LOSS COMP 0 MO.DA HR,MN PERIOD RAIN EXCS LOSS COMP 0

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS								
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9
				.10	.15	.20	.25	.30	.35	.40	.50	1.00
HYDROGRAPH AT	1	.29	1	191.	287.	383.	479.	574.	670.	766.	957.	1915.
	(.75)	(5.42)	8.13)	10.84)	13.55)	16.26)	18.97)	21.69)	27.11)	54.21)
ROUTED TO	2	.29	1	146.	229.	315.	403.	492.	582.	671.	857.	1860.
	(.75)	(4.14)	6.50)	8.91)	11.41)	13.94)	16.47)	18.99)	24.26)	52.67)



SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1

ELEVATION
STORAGE
OUTFLUM

INITIAL VALUE
347.60
73.
4.

SPILLWAY CREST
347.60
73.
4.

TOP OF DAM
350.70
108.
1292.

RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLUM CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLUM HOURS	TIME OF FAILURE HOURS
.10	348.50	0.	83.	146.	0.	40.50	0.
.15	348.60	0.	86.	229.	0.	40.50	0.
.20	349.06	0.	89.	315.	0.	40.50	0.
.25	349.29	0.	91.	403.	0.	40.50	0.
.30	349.49	0.	94.	492.	0.	40.50	0.
.35	349.68	0.	96.	582.	0.	40.50	0.
.40	349.84	0.	97.	671.	0.	40.50	0.
.50	350.15	0.	101.	857.	0.	40.33	0.
1.00	351.16	.46	113.	1860.	1.00	40.33	0.




PHOTO 1: Centerline of Dam from the Left Abutment




PHOTO 2: Downstream Slope from Right Abutment




PHOTO 3: Upstream Slope from Left Abutment



PHOTO 4: Wavewash on Upstream Slope




PHOTO 5: Erosion Area



PHOTO 6: Marshy Area near Downstream Toe and Emergency Spillway



PHOTO 7: Inlet Pipe



PHOTO 8: Outlet Pipe



PHOTO 9: Emergency Spillway



PHOTO 10: Guide Levee between Farm Pond and Lagoon




PHOTO 11: Farm Pond



PHOTO 12: Lagoon




PHOTO 13: Floodplain Downstream from Dam



PHOTO 14: Dwelling Downstream of Dam



PHOTO 15: Uninhabited Dwelling Downstream of Dam .

DATE
ILME